

FIG. 1 (PRIOR ART)




FIG. 2 (PRIOR ART)




FIG. 3 (PRIOR ART)

INITIAL SETTING VALUE	INITIAL VALUE	INITIAL SETTING VALUE	INITIAL VALUE
0H	0001H	8H	0010H
1H	5500H	9H	5000H
2H	0002H	AH	0020H
3H	2A00H	BH	2001H
4H	0004H	CH	0040H
5H	5400H	DH	4002H
6H	0008H	EH	0080H
7H	2800H	FH	0005H

FIG. 4 (PRIOR ART)

LFSR(n)	LFSR(n+1)
R15	R7
R14	R6
R13	R5
R12	R4
R11	R3
R10	R2
R9	R1
R8	$R15 \oplus R11$
R7	$R14 \oplus R10$
R6	$R13 \oplus R9$
R5	$R12 \oplus R8$
R4	$R11 \oplus R7$
R3	$R10 \oplus R6$
R2	$R9 \oplus R5$
R1	$R8 \oplus R4$

FIG. 5




FIG. 6




FIG. 7

LFSR(n)	LFSR(n+1)	USB	LSB
R15	$R14 \oplus R10$		
R14	$R13 \oplus R9$		
R13	$R12 \oplus R8$		
R12	$R11 \oplus R7$		
R11	$R10 \oplus R6$		
R10	$R9 \oplus R5$		
R9	$R8 \oplus R4$		
R8	$R7 \oplus R3$	$R7 \oplus R3$	$R15 \oplus R11$
R7	$R6 \oplus R2$	$R6 \oplus R2$	$R14 \oplus R10$
R6	$R5 \oplus R1$	$R5 \oplus R1$	$R13 \oplus R9$
R5	$R15 \oplus R11 \oplus R4$	$R15 \oplus R11 \oplus R4$	$R12 \oplus R8$
R4	$R14 \oplus R10 \oplus R3$	$R14 \oplus R10 \oplus R3$	$R11 \oplus R7$
R3	$R13 \oplus R9 \oplus R2$	$R13 \oplus R9 \oplus R2$	$R10 \oplus R6$
R2	$R12 \oplus R8 \oplus R1$	$R12 \oplus R8 \oplus R1$	$R9 \oplus R5$
R1	$R15 \oplus R7$	$R15 \oplus R7$	$R8 \oplus R4$